## Galvanometer



## Measuring direct currents.

- magnetic moment  $\vec{\mu}$  (along needle)
- magnetic field  $\vec{B}$  (toward right)
- torque  $\vec{\tau} = \vec{\mu} \times \vec{B}$  (into plane)

